

Super H.D.[™]

Water Soluble, Safety Solvent



KEY FEATURES

Electronic Air Filters, Fan Blades and Blowers

Permanent Filters, Refrigeration Parts

Heating Parts, Air Ducts and Grills

Non-Corrosive, Non-Flammable

Cleans, Degreases, Deodorizes

Part #	Product	QTY	Size
H-1501	Safety Solvent	4	1 Gal Bottle
H-1505	Safety Solvent	1	5 Gal Pail
H-1555	Safety Solvent	1	55 Gal Drum



Easily Removes Grease, Soot, Grime, Oil, Tobacco Tars, Wax, Carbon, Gummy Dust...and Many Other Stubborn Deposits.

Directions For Use:

- Super H.D. may be applied by dipping, swabbing or low or high pressure sprayer.
- For cleaning electronic filters, turn unit and fans off. Dilute Super H.D. with 2 parts water. Spray liberally and allow to penetrate for 5 minutes, rinse thoroughly with water.
- To clean other hard surfaces, dilute with 4 parts water for baked on residue or grease.
- Dilute with 8-10 parts water for oils, dust and grime.
- Do not use on glass.

DANGER: Causes severe skin burns and eye damage.

Do not breathe mist/vapors/spray. Wash face, hands, and any exposed skin thoroughly after handling. Wear protective gloves/protective clothing/eye protection/face protection.

FIRST AID: IF SWALLOWED: Rinse mouth. Do NOT induce vomiting. IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water/shower. Wash contaminated clothing before reuse. IF INHALED: Remove person to fresh air and keep comfortable for breathing. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER/Doctor.

Store locked up. Dispose of contents and container in accordance with all local, regional, and national regulations.

Contains [CAS]: Sodium metasilicate [6834-92-0], dipropylene glycol monomethyl ether [34590-94-8].

