

H.B.30



KEY FEATURES

Meets Manitowoc's Spec. GES-6 For Ice Machine Cleaner

Food Safe

Dissolves Scale

All Ingredients Meet F.C.C. Specs

USDA Accepted

Part #	Product	QTY	Size
H-316	Ice Machine Cleaner	12	16 fl. oz. Bottle



Directions For Use:

Follow equipment manufacturer's cleaning instructions. If not available, use the following as a guide:

- 1. Read entire label & Safety Data Sheet before use.
- 2. Drain machine and refill with fresh water.
- 3. Turn off refrigeration and leave pump in operation if possible.
- 4. Add H.B. 30 to circulating water at the rate of 3 6 ounces per gallon.
- 5. Circulate for approximately 30 minutes, brushing solution on surfaces not contacted by circulating solution. Extra heavy scale may require repeat application. Clean drums by mixing 8 ounces H.B. 30 with 2 quarts water and brush on scaled surfaces.
- 6. After cleaning, drain and flush thoroughly with fresh water.

DANGER: May be corrosive to metals. Causes severe skin burns and eye damage. Harmful if swallowed.

Keep in original container. Do not breathe mist/ vapors/spray. Wash face, hands, and any exposed skin thoroughly after handling. Wear protective gloves/ protective clothing/eye protection/face protection.

FIRST AID: IF SWALLOWED: Rinse mouth. Do not induce vomiting. IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water/shower. Wash contaminated clothing before reuse. IF INHALED: Remove person to fresh air and keep comfortable for breathing. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing. Immediately call a POISON CENTER/doctor.

Store locked up. Dispose of contents and container in accordance with all local, regional, and national regulations.

Contains [CAS]: Phosphoric acid [7664-38-2], citric acid [77-92-9], poloxamer [9003-11-6].





